

School Facilities and Organization
INFORMATION AND CONDITION OF SCHOOLS
Detailed Condition Assessment by Building

Reporting Year 2024-2025

WOODLAND

91.70%

WOODLAND HIGH SCHOOL (NEW) - MAIN BUILDING

Building Details

PROFILE TYPE High School - Multi-Story

NUMBER OF FLOORS 2

BOARD ACCEPTANCE DATE 6/26/2017

CHARACTERISTICS Occupied

ANNUAL REVIEW COMPLETED BY District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	7	91.70	District	3/27/2025
2023-2024	6	93.46	Consultant	Not Reported
2022-2023	5	Not Reviewed	Incomplete	Not Reported
2021-2022	4	Not Reviewed	Incomplete	Not Reported
2020-2021	3	Not Reviewed	Incomplete	Not Reported
2019-2020	2	Not Reviewed	Incomplete	Not Reported

The next certified BCA is due: 2029

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2014	Area 1	149,881	149,881	149,881		6/26/2017
	Building Totals	149,881	149,881	149,881	_	

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		100.00% Excellent
Slabs on Grade	Standard Slabs on Grade	A4010		100.00% Excellent
	Pits and Bases	A4040		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		100.00% Excellent



School Facilities and Organization INFORMATION AND CONDITION OF SCHOOLS

WOODLAND

91.70%

Detailed Condition Assessment by Building

Reporting Year 2024-2025

WOODLAND HIGH SCHOOL (NEW) - MAIN BUILDING

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Superstructure	Floor Construction	B1010		90.00% Good
	Roof Construction	B1020		90.00% Good
	Stairs	B1080		100.00% Excellent
Exterior Vertical Enclosures	Exterior Walls	B2010		100.00% Excellent
	Exterior Windows	B2020		100.00% Excellent
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		90.00% Good
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		100.00% Excellent
	Overhead Exterior Enclosures	B3080		90.00% Good
nterior Construction	Interior Partitions	C1010		100.00% Excellent
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		100.00% Excellent
	Suspended Ceiling Construction	C1070		100.00% Excellent
nterior Finishes	Wall Finishes	C2010		90.00% Good
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		90.00% Good
	Stair Finishes	C2040		90.00% Good
	Ceiling Finishes	C2050		100.00% Excellent
Conveying	Vertical Conveying Systems	D1010		90.00% Good
Plumbing	Domestic Water Distribution	D2010		90.00% Good



School Facilities and Organization INFORMATION AND CONDITION OF SCHOOLS

WOODLAND

91.70%

Detailed Condition Assessment by Building

Reporting Year 2024-2025

WOODLAND HIGH SCHOOL (NEW) - MAIN BUILDING

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Plumbing	Sanitary Drainage	D2020		62.00% Fair
	Building Support Plumbing Systems	D2030		90.00% Good
	General Service Compressed-Air	D2050		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Cooling Systems	D3030		90.00% Good
	Comments:	System issues appearance last assessment observed and comm	nt per conditions	
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Facility Power Generation	D5010		90.00% Good
	Comments:	Conditions have app since last assessmer	·	
	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
	Comments:	Driver faults appear resolved.	to have been	
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		62.00% Fair
	Deficiencies:	Static on Lines		



School Facilities and Organization INFORMATION AND CONDITION OF SCHOOLS

WOODLAND

91.70%

Detailed Condition Assessment by Building

Reporting Year 2024-2025

WOODLAND HIGH SCHOOL (NEW) - MAIN BUILDING

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Communications	Causes:	Other		
	Comments:	Announcement speakers are crackling in certain areas and have not been able to be fixed		
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Fire panel PA doesn	't work correctly	
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		62.00% Fair
	Electronic Surveillance	D7030		62.00% Fair
	Detection and Alarm	D7050		30.00% Poor
	Deficiencies:	Devices Not Working	g	
	Causes:	Equipment Obsoles	cence	
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Vehicle and Pedestrian Equipment	E1010		90.00% Good
	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		90.00% Good



School Facilities and Organization
INFORMATION AND CONDITION OF SCHOOLS
Detailed Condition Assessment by Building
Reporting Year 2024-2025

WOODLAND

91.70%

WOODLAND HIGH SCHOOL (NEW) - MAIN BUILDING