

A photograph of a modern school building with a courtyard. The building has a mix of tan and grey tones. In the foreground, there is a paved courtyard with some greenery and a few people walking. The sky is blue with some clouds. The text is overlaid on the image.

Woodland Public Schools

Facilities and Safety Report
November 2017

FACILITIES REPORT



Holiday Shutdown Planning In addition to our standard annual cleaning activities, maintenance, custodial, grounds and contractors will be completing the following work. Below is a brief summary and schedule of these items.

- **Storm Drains and Drywells, 12/21** - Clean out storm drains at 3 schools, clear drywell between WPS and WMS, locate and clean drywell by business office.
- **Replenish EWF, WPS and WIS (schedule pending delivery availability)** – Add Engineered Wood Fibers to WIS, WPS main and alternate playground areas to meet fall protection standards
- **Locks WMS (schedule pending availability)** – Start blanking exterior doors and change exterior keys at WMS to enhance school security
- **HEPA install Ceramics lab** – Installation of two Fan Filter Units (FFU's) to reduce ceramic particulate in classroom environment and create a healthier environment
- **Annual SWCAA boiler testing 12/26** – Complete annual stack testing and annual Southwest Clean Air Agency compliance inspections and reports
- **Resurface Green Gym floor 12/20–12/23** Install new water based finish coat to gym floor
- **Electrical repairs 12/18 -12/22** Install permanent conduit where extension cords have been used, wire in new FFU's WHS, and miscellaneous other electrical jobs to support other repairs and shutdown activities
- **House tear down 2280 Lewis River Rd 12/18 – 12/23** Demo house next to WIS, clear site of vegetation, grade site, remove fences and lay crushed rock.

Facilities Report Continued



- **Cameras WPS/WMS 12/18 – 12/29** Complete balance of Exterior cameras WIS, Repair 3 cameras WMS
- **Chair rail wall WHS (in progress)** -Repair area where chairs have been stored, install chair rail to protect newly repaired surface
- **CNC to WHS (in progress)**– Move Mazak CNC (Computer Numerical Control) milling tool to WHS auto shop, relocate existing lathe, milling tool and tire balancer to accommodate new tool install.
- **Wall and ceiling repairs WMS, WHS (In progress)** - Ceiling green hall (2), bathroom and room 430. Stage area WHS
- **Kitchen items – 12/18 – 12/29** Repair wall WPS, maintenance on freezer WMS and hot line repair WHS
- **Annual department training 12/19** – OSHA occupational safety training for entire team, ladder, roof, hazcomm, etc.
- **Installation of weather stations WHS, WMS** to support Emergency planning activities
- **Install remote communication box WHS stadium** to support remote operation of field lighting controls
- **Sidewalk install WPS, WHS 12/18-12/22** Install sidewalk to aid special Education students better egress to buses and island bridge WHS

FACILITY CHARTS – POWER COST AND WORK ORDER STATUS





FACILITY CHARTS – WATER USAGE


WHS, WIS, WMS, WPS



Water charts are updated every two Months, next update to these charts in January 2018



The WMS chart has been reconfigured to include the following 7 meters: 755 park high and low flow, BO and Team High, Pit house, buss barn, athletic field and DO. All of these meters are totaled on the WMS graph but each data point is recorded separately to aid in identifying leaks.



SAFETY REPORT

Accidents for the month

There were a total of 9 student injuries and 4 staff incidents/accidents

Staff Accidents/Incidents

- WPS - Student behavior caused injury to IA (3 events)
- Yale – One employee slipped on stairs

Student Accidents/Injuries (8)

- WPS - Student pushed by another student injured rump
- WIS – Student slipped on stair tread hit bottom
- WIS - Student kicked ball lost footing and hit head on gym floor
- WIS – Student slipped on portable ramp, scraped knee and hand
- WIS – Closing blinds, student pulled too hard on rod and dislodged valance and struck arm
- WHS – Student's hair burnt by torch (careless handling)
- WHS – Student rolled ankle during basketball, sprain
- WHS – Student's knee popped, fractured leg
- WHS – Student missed bottom step, bruise and 2 minor abrasions

SAFETY CHARTS

