

A wide-angle, slightly elevated photograph of a modern school campus. The main building is a long, single-story structure with a light-colored facade and a series of windows. In the foreground, there is a paved courtyard with several people walking. A car is visible in the bottom right corner. The sky is blue with scattered white clouds. The text is overlaid on the image in a green, italicized font.

Woodland Public Schools

Facilities and Safety Report
For September 2019

FACILITIES REPORT

Automated Lockdown Announcement – Over the next couple of weeks we will be looking into automating the lockdown announcement at all schools. This will be accomplished by creating a prerecorded message (much like Humoctopus) in the Informacast program and tying it to all of the schools lockdown hardware. This will give the offices the ability to quickly get the buildings into Lockdown (flip of a switch) without having to use the paging system should the need arise.

Yale School Fencing The current fencing at the Yale School only parallels along the road (Lewis River Rd.) and terminates to the building on the east end near the entry door. We will be extending this fence on the west and north side of the sports field, so it covers 360 degrees. This will keep the occasional loitering cows and other animals from entering this area of the school.

Upcoming Halloween No Student Days Facilities will take advantage of the time to complete some maintenance activities including:

- Moving and anchoring equipment in the WHS auto shop
- Installing a commercial water heater above the commons at WMS
- Resurfacing the floor in the WMS kitchen
- Elevator fire and recall test (NFE and WHS)
- Repair section of sprinkler piping in CES
- Repair section of sprinkler piping WMS
- Adding locking hardware to NFE classroom doors

FACILITIES REPORT

Reunification Drill March 2020 - We are planning to run a reunification drill in the spring to test our reunification program. The plan will be to reunify a group of students (approximately 75) from WMS to WHS gym. We will set up the reunification point at the entrance to the WHS gym. The goal of this is to test the following programs in the event of an actual emergency.



- Deploy busing to the school in sufficient numbers
- Check reunification policy/procedure/strategies
- Set up of the reunification point
- Coordination of the police and first responders
- Reunification equipment checks
- Traffic control

Over the next few months, we will be honing our skills and training in these areas. More information to follow...

SOP and Policy Revisions- Completed annual update of the district's *Emergency Operations Plan* (procedure 3432) and completed an edit to Pesticide Notification Policy (6895) and the associated procedure.

Urgent Repair Grant 909 - I have applied for the Urgent Repair Grant for two areas of WMS. The first is to replace all of the gutters and downspouts on the two main buildings of the middle school (1930 linear feet) and the second replaces the water piping main from Park Street to the Green Gym, Auditorium and Wood/Metal Shops.





FACILITY CHARTS – POWER COST AND WORK ORDER STATUS




FACILITY CHARTS – WATER USAGE

WHS, NFE, WMS, CES

Note
 Water charts are updated every two months. Next update to these charts in November 2019.



The WMS chart has been reconfigured to include the following 7 meters: 755 Park high and low flow, BO and Team High, PIT house, bus barn, athletic field and DO. All of these meters are totaled on the WMS graph, but each data point is recorded separately to aid in identifying leaks.



Safety Summary

Staff Accidents/Incidents

(No data available)

Student Accidents/Injuries (11)

CES – Fell on play structure, fractured arm

CES – Hit in hand with ball, sprained wrist

CES – Tried to sit in walker, lost balance and tipped backward, emotionally upset , no injury noted

WMS – Football soft tissue injury to leg

WMS – Soccer finger injury

WMS – Knee injury during soccer practice when standing up

WHS – Football knee injury sprain

WHS- Sprayed brake cleaner in eye, sent to urgent care

WHS – Hit back of head during soccer, concussion screen complete, went to ER cleared by doctor

WHS – Touched hot saw blade, minor burn to finger

WHS – Strained back during soccer practice

SAFETY CHARTS

