
# Woodland Public Schools


Facilities and Safety Report
January 2021

## **FACILITIES REPORT**


- Completed 400 feet of gutter replacement on the north side of WMS.
- Completed annual fire system inspections and backflow testing.
- Transferred fire system monitoring to Johnson Controls Fire.
- Completed main water line replacement in the green gym at WMS.
- Installed 4 new bottle fill stations (WMS,CES, NFES).
- Installed TEAM High portable building; occupancy expected 3<sup>rd</sup> week of February.
- Completed annual boiler inspections and annual clean air agency report.
- Completed carpet installs at NFES room 211 and WMS room 306.
- Installed new 2HP garbage disposal in WMS kitchen.
- Completed annual bleacher inspections.
- Prepping all schools for the return of students (PPE, physical arrangement of furniture, etc.).


## FACILITY CHARTS - POWER COST AND WORK ORDER STATUS






## FACILITY CHARTS WATER USAGE WHS, NFES, WMS, CES









The WMS chart includes the following 7 meters: 755 Park high and low flow, BO and TEAM High, PIT house, bus barn, athletic field, and DO. All of these meters are totaled on the WMS graph, but each data point is recorded separately to aid in identifying leaks.

#### Note

Water charts are updated every two months. Next update to these charts in the March 2021 report.





## Safety Summary

### **Staff Accidents/Incidents**

NFES -Staff member caught shoe on floor, tripped and bruised their left knee.

CES – Escalated student pushed employee, fell backwards and strained their back.

## **Student Accidents/Injuries**

WMS – Escalated student bit own arm, minor skin abrasion.