



Woodland Public Schools



Facilities and Safety Report

May 2022

Facilities Report

- Entry Cameras - Installed entry cameras for the District and NFES offices. Over the next few weeks WHS and Yale schools will also be installed. This is a dedicated camera and monitor that provides office workers a preemptive view of persons approaching the school offices.
- Improved Office Security - Met with Stanley Security for hardening office security access and egress. The goal of this project is to improve office security, and provide egress for office workers in the event that they would need to flee the area while still maintaining the second level time barrier. The upgrades also include redundant security controls.
- Reader Boards - Finished the installation of Columbia's new LED full color reader board.
- Met with the City regarding proposed changes to 5th Street. We still plan to stop traffic at the 90 bend in the road, but the City was reluctant to allow the District to block any part of the road. This means the parking area for the portables will be slightly to the east of the City turnaround, which should be OK. This small modification to the plan has the same end result, and accomplishes the safety goals desired.
- Summer Work – In addition to the regular deep cleaning and painting projects District-wide, there are a total of 82 line items scheduled this summer. These are preventive/corrective maintenance and projects, including the revisions to 5th Street, HVAC ESSER projects, and a surplus sale.


FACILITY CHARTS – POWER COST AND WORK ORDER STATUS




FACILITY CHARTS - WATER USAGE

WHS, NFES, WMS, CES


COLUMBIA



WMS




WHS - IRRIGATION




Note

Water charts are updated every two months. Next update to these charts in the June 2022 report.

NORTH FORK



WHS BUILDING



The WMS chart includes the following 7 meters: 755 Park high and low flow, BO and Team High, PIT house, bus barn, athletic field and DO. All of these meters are totaled on the WMS graph, but each data point is recorded separately to aid in identifying leaks.

Safety Summary

Staff and Student Incidents

Staff Accidents/Incidents - 4

- WMS - Custodian slipped on dumpster ramp- bruised
- CES - Aide lost balance playing with student, hit pavement with knees and cheekbone- no injury
- NFES - Aide was pushed and grabbed by student- bruised forearm
- WMS - Cook burned by hot water in kettle- burned wrist

Student Accidents/Injuries - 7

- NFES - Student caught finger in closing door- no injury
- NFES - Student running and looking backwards ran into tetherball pole- 10 stitches
- NFES - Student ran into bar head first and hit nose- nosebleed
- CEC - Student scraped knee on sharp edge of stage outlet-cut near knee
- WMS - Track student running hurdles fell- no injury reported, but doctor put her in walking boot
- WHS - Student cut by a pruner- 5 stitches
- WHS - Student running tripped and fell onto knees and hip- bruised and scraped